

Original	Site	Original	Confirm	6 D's	Original	Original	Planting Notes	Replant	Replant	Replant
Tree		Tree Species	Reason for		Tree	Tree		Species	Easting	Northing
Position			Removal		Easting	Northing				
O/S 4	CLUB STREET	Sorbus intermedia	Structural Integrity	Dangerous	434750.46	386003.08	TR: Replanting Same location o/s 4 club street on the corner in NEW PIT.	Gleditsia triacanthos 'Sunburs	434750.46	386003.08